## PPM

"Part Per Million" is a unit of measurement used to describe very small amounts of something in a much larger amount of something else. 1 per 1,000,000

Parts Per Million (PPM)	Percent (%)
0	0
5	0.0005
50	0.005
500	0.05
5000	0.5